



NOTE : MF = METAL FILM RESISTORS
FP = FLAME PROOF RESISTORS
EHS = ESD SENSITIVE RESISTORS








CITRONIC LTD. • ©
HALIFAX ROAD
BOXHILL
NEWKSHAM
WILTSHIRE SN12 6UB

NOTE: MF = METAL FILM RESISTORS
 FP = FLAME PROOF RESISTORS
 FUS = FUSIBLE RESISTORS

A
 B
 C







for PDX900 OR PFX450 AMP (EARLY TYPE)

PC1061/2 ISSUES UP TO F (OLD TYPE) CONVERSION TO
MJE340 & 2N5416 DRIVERS.

① Change TR3 & TR4 from MPSW43 to MJE340s.


MJE340

CONFIGURATION.




FRONT SIDE.

MPSW CONFIGURATION.
(PINOUT TOP VIEW)



② Change TR5 from MPSW43 to 2N5416 Metal Can Type.

2N5416 CONFIGURATION.
(TOP VIEW).



(NOTE:- CONNECTOR JOINED TO CAN)

MPSW CONFIGURATION
AS ABOVE.

(ALSO FITTED MICA SPACER &
HEATSINK TO 2N5416)

③ Change DS, D7, D2 (IN4004) to BA157 Diodes.

④ Tag 2nd cap (0.0022μf) Ewox Box Across D7.

⑤ Change D6 (IN4004) to IN4118 Diode.

Test, Check DC. offset & BIAS.